

24-January-97

**CAMERON BALLOONS LTD (THUNDER & COLT)
SERVICE BULLETIN: ENVELOPES SB3**

**Subject: THUNDER AND COLT
TRIVENTS**

Title: Reinforcement of attachments on the Trivent flap.

**Parts affected: SN 3528, CN 3553, CN 3688, CN 3719, CN 3746, CN 3825
CN 3833, CN 3835, CN 3845, CN 3886, CN 3891, CN 3922
CN 3949, CN 3956, CN 4026.**

**Reason for modification: To ensure that all the attachments on the centreline
of the flap are adequately reinforced.**

Classification: CAA MANDATORY

**Compliance: Inspection of red line attachment to the TRIVENT flap, to be
performed before every flight, until reinforced.
The inspection may be performed by the Pilot.
Reinforcement to be performed, within twenty flying hours
of receiving this bulletin.**

**Accomplishment Instructions: Inspect the balloon as described in section A.
Add reinforcements as described in section B.**

If in doubt please contact the factory.

**Thunder and Colt
St John's Street
Bedminster
Bristol
BS3 4NH**

**Tel +44 (0)117 9532772
Fax +44 (0)117 9663638**