

**CAMERON BALLOONS LTD (THUNDER & COLT)**

**SERVICE BULLETIN: SB5**

Subject: **Super Shadow / Single Super Shadow / Stealth Burners**

Title: **A) Replacement of Main Blast Valve Stems.  
B) Blast Valve free Movement check.**

Parts affected: **Super Shadow / Single Super Shadow / Stealth Burners  
from March 1997 ( see Appendix I ).**

Reason for  
Modification/  
Inspection. **A) Incorrect surface finish on blast valve stems.  
B) Lack of Free Movement in the blast valve.**

Modification  
Classification: **Highly Recommended**

Compliance: **A) Replacement in accordance with CBL/TN/JD/1514.  
Remedial action must be taken before the next annual  
inspection.  
B) Inspection in accordance with CBL/TN/JD/1573**

Possible  
Consequence of  
Non-Compliance: **Blast Valve could stick open requiring remedial action in  
accordance with Cameron Balloons Flight Manual Issue 7,  
Section 3 - Emergency Procedures Para. 3.8**

Accomplishment  
Instructions. **CBL/TN/JD/1514 Issue C.**

**If in doubt please contact the factory.**

**Cameron Balloons Ltd /Thunder and Colt  
St John's Street  
Bedminster  
Bristol  
BS3 4NH**

**Tel +44 (0)117 9637216  
Fax +44 (0)117 9661168**