

**CAMERON BALLOONS LTD and THUNDER & COLT**

**SERVICE BULLETIN: SB9**

Title: **Return to Service of Titanium Propane Cylinders.**

Parts affected: **Titanium propane cylinders types:**  
**CB2380, serial numbers BT0005 onwards.**  
**CB2383, serial numbers BT0001 to BT0010, BT0012 to BT0014,**  
**BT0016 to BT0033 onwards.**

Reason **Embodiment of Cameron Modification C274 Issue 2.**

Classification: **Recommended.**

Compliance: **Receipt of cylinder release to service following rework.**  
**Note: An 'S' suffix to the part number denotes embodiment of**  
**Cameron Modification C274 Issue 2. The 'S' suffix is**  
**engraved on cylinder identification plate.**

Accomplishment Instructions. **Cylinder Modification carried out by Cameron Balloons.**  
**A check for the presence of the above noted Cameron-applied**  
**suffix must be made before use.**

**If in doubt please contact the factory.**

**Cameron Balloons Ltd /Thunder and Colt**  
**St John's Street**  
**Bedminster**  
**Bristol BS3 4NH**

**Tel +44 (0)117 9637216, fax +44 (0)117 9661168**